

1999-ON MAZDA MX-5 MIATA

PLEASE NOTE: 1999 MX-5 MIATA CONVERTIBLES WERE FIRST INTRODUCED FOR SALE IN SPRING 1998. ALL 1999-ON MX-5 MIATA MODELS WERE ORIGINALLY EQUIPPED WITH HEATER/DEFOGGER GLASS WINDOWS, WITH NO ZIPPER.



2960	1999-On	Mazda MX-5 Miata Top with Heater/Defogger Glass Window, No Rain Rail, No zipper.	6.5	(O.S.)*18
2961	1999-On	Mazda MX-5 Miata Top with Heater/Defogger Glass Window, With Rain Rail, No Zipper. Glass heatsealed into 2960 and 2961 Tops. Made with Partitioned Cable Sleeve, U.S. Patent 6,022,064; other patents pending. No Black Bezel around glass. Made with one listing at #2 Bow, and extended inner panel from window assembly as original. (No listing at Rear Bow). OE style wire connectors soldered to glass to connect to factory wiring harness. 2960/2961 Tops made in OE style with no separate window assembly. (Glass cannot be replaced.)	5.75	(O.S.)*20

Tops with Zipper Window

2962	1999-On	Mazda MX-5 Miata Top with Heater/Defogger Zipper Glass Window, No Rain Rail.	6.5	(O.S.)*18
2963	1999-On	Mazda MX-5 Miata Top with Heater/Defogger Zipper Glass Window, With Rain Rail. Two Piece Top and Window Assembly Design. Glass heatsealed into 2962 and 2963 Tops. Made with Partitioned Cable Sleeve, U.S. Patent 6,022,064; other patents pending. No Black Bezel around glass. Made with one listing at #2 Bow, and extended inner panel from window assembly as original. (No listing at Rear Bow). Made with Single Ring Pull Zipper. After making certain defogger switch is OFF, Glass can be lowered when Top is raised by unzipping zipper and manually lowering glass. Zipper does NOT have to be unzipped to lower top. OE style wire connectors soldered to glass to connect to factory wiring harness. HD297 Replacement zip in Glass window assembly available	5.75	(O.S.)*20

CAUTION: FOR 2960,2961,2962,2963 TOPS, BOW END CAPS SUPPLIED IN BOX MUST BE INSTALLED AT END OF #2 BOWS OR WARRANTY IS VOID. 1999-On MX-5 Miata Top frame components can cause pinching, abrasion damage and cuts and holes to occur to 2960, 2961, 2962 and 2963 Tops. Robbins cannot be held responsible for any damage to our products caused by top frame components.

Original Topping for 2960, 2961, 2962 and 2963: 1999: Black/Black and Light Tan/Black Cabrio Grain German Vinyl. 2000: Black/Black, Light Tan/Black and Light Beige/Black Cabrio Grain German Vinyl.

2959Z	1999-On	Mazda MX-5 Replacement Front Top Only for 2962/2963 Tops. (No Rain Rail supplied). Made with 1/2 Single Ring Pull Zipper to zip into rear window assembly.	5.0	7
HD297	1999-On	Mazda MX-5 Replacement Heater/Defogger Glass Window for 2962/2963 Tops. (No Rain Rail supplied). Made with Single Ring Pull Zipper to zip into rear window assembly.	4.5	(O.S.)*13
Cables 2960	1999-On	Side cables for 1999-On Miata. Stainless steel cable with metal end and long spring, pair..	.5	1
Rain Rail	1999-On	Rain Rail Assembly Only. Labor time does NOT include hours to remove old top and window assembly, or hours to install top and window assembly on Miata.	1.0	3