

Item No.	Year		Approx Inst Hours	Bow Height	Approx. Weight (Lbs)
SAAB					
2725	1986-94	Saab 900, 900S Top. Made as original with vinyl binding for 1987-1991 models.	8.5	23	9
2725C	1986-94	Saab 900, 900S Top. Made as original with cloth binding for 1992-93 models. Supplied with strip of matching binding material to recover rear bow exterior trim piece. For Headliner order 925L. Alignment Guide Holes Pre-Drilled.	8.5	23	9
HD272	1986-94	Tinted Glass With Heater/Defroster Window for 2725, 2725C Tops. Glass Heatsealed into topping. Headliner hides backing cloth color. Glass fits models with last eight digits of V.I.N. beginning with H7011950. Zipper. (Installation time for top and window.)	12.0†		(O.S.)*15
925L	1986-94	Saab 900, 900S Headliner. Made in original style black velour headliner material, plastic extrusions, vinyl binding, and elastic straps with black Durable fasteners.	3.0		7
CABLES 2725		87-93 Saab Side Cables, pair.	1.0		1

Original Topping for 2725: 1987-91 Black/Black Sonnenland German Cloth. 1992-93 Saab Tan/Tan and Black/Black Sonnenland German Cloth. Headliner Charcoal Velour.

CAUTION: Saab has issued Service Bulletin 03/93-0316 for 1987-93 Saab convertibles advising that top frame components can cause pinching of the top, and that abrasion damage, cuts, and holes can occur. Robbins cannot be held responsible for any damage to our products caused by the problems described above.



SAAB 1996-ON

2728R	1996-98	Saab 900 Top, C.T.S., (No Glass Window installed). Begins with VIN #T7006412 (10th digit of VIN). Made with original style Hand-Rolled Binding, no stitching on seams. Alignment marks on Top for location to install reusable factory heater/defroster glass window, weatherseal and retainers. Headliner attaches with Velcro to metal retainer. (Headliner not supplied).	16.0	9
--------------	----------------	--	------	---

CAUTION: Saab has issued multiple Service Bulletins regarding pinching and abrasion damage in 1994-98 Saab tops caused by the design of the top frame, body components and top. Robbins cannot be held responsible for any damage to our products caused by the problems described above.

Original Topping for 2728R and 2732C Black, Blue and other colors Sonnenland A-S German Cloth with Black backing.

2732C	1998-02	Saab 9-3 Top, C.T.S. (No Glass Window installed). Original Heater/Defroster Glass can be reinstalled in top. Made with original style double fold Cloth Binding. Alignment marks on Top for location to install glass.	16.0	9
--------------	----------------	---	------	---

CAUTION: Saab has issued Service Bulletins regarding problems with top frames, and wrinkles, pinching and abrasion damage to top Robbins cannot be held responsible for wrinkles or other damage to tops caused by the design of the top or top frame.

WARNING 2728R & 2732C Tops: Be extremely careful removing clips that attach glass, rubber weatherseal and metal retainers to old top. Do not lose any clips and be careful not to scratch or chip the glass. **Place shop blanket on bench to protect glass, and be extremely careful when installing glass, rubber weatherseal and retainers in top with clips.**

NOTE 2728R & 2732C Tops: Wrinkles and gathering in topping can occur in rear window area due to the original Saab design of the top and top frame system.